




# MAN ES 12V 32/40 G

# Piston, Under Crown and Rings Cleanliness



- Low deposits on the piston, under crown and rings







# Cold Space Cleanliness



- No signs of sludge build in engine cold spaces



# Minimal Liner and Bearing Wear

